

# SF61B

## Accessory Guide

### Wearables

Accessory Name	Part Number	Description	Backward Compatible with SF51
Magnet End-Cap and Belt Loop	SF61-MAG-S001	This two-piece kit secures the scanner to your belt with magnetic force. Simply attach the belt loop with magnet to your belt, and affix the magnetic end-cap to the SF61B mobility scanner. This provides a quick and convenient attach/release method. A small plastic tool is included for installation/removal.	No
Ring End-Cap and Wrist Strap	SF61-RIN-S001	This two-piece kit includes a end-cap with ring that affixes to the SF61B mobility scanner, and a convenient wrist strap with cord-tightener. Simply thread the wrist strap through the ring, and the scanner can be conveniently worn around your wrist or arm--yet easily stowed away when both hands are needed. A small plastic tool is included for installation/removal.	No
Belt Loop, Standard	825-171-002	Belt loop with snap closure, allowing the SF61B to be conveniently attached to your belt. Note: Does not include the scanner magnet end-cap (see SF61-MAG-S001 for the entire kit).	Yes
Belt Clip, Industrial	825-172-002	A more heavy-duty version of the above belt loop, this industrial clip allows the SF61B to be conveniently attached to your belt. Note: Does not include the scanner magnet end-cap (see SF61-MAG-S001).	Yes
Chest Strap Holder	825-173-002	Designed for high-volume scanning in the DC or warehouse, this chest strap includes an adjustable waist with heavy-duty side squeeze buckle, and suspender with magnetic attachment. Fully adjustable.	Yes

# SF61B

## Accessory Guide



### Holders and Chargers

Accessory Name	Part Number	Description	Backward Compatible with SF51
USB Charger, Single Bay 	SF61-UPK-S001	Charge a single SF61B mobility scanner via a USB port. (Requires a minimum 5V power source.)	No
Charge Cradle, Single Bay 	871-221-001	Charge cradle accommodates a single SF61B or SF51 mobility scanner. Includes a mounting plate for fixed-mounting onto a countertop or wall. Separate power supply (851-089-306) must be purchased separately.	Yes
Charge Cradle, Quad Bay 	871-222-001	Charge cradle accommodates up to four SF61B or SF51 mobility scanners. Includes a mounting plate for fixed-mounting onto a countertop or wall. Separate power supply (851-088-201) must be purchased separately.	Yes
FlexDock Cup, Dual Charge 	213-007-001	Supports the charging of two SF61B scanners when snapped into the bay of a FlexDock base (ordered separately--see below).	No
FlexDock Base, Quad Charge 	852-916-001	Provides four bays for charging. When combined with the FlexDock dual-charge cup above, this base can support the simultaneous charging of up to eight SF61B mobility scanners. FlexDock cups, power supply (851-064-327), and country-specific line cord must be ordered separately.	No
FlexDock Base, Dual Charge 	852-918-001	Provides two bays for charging. When combined with the FlexDock dual-charge cup above, this base can support the simultaneous charging of up to four SF61B mobility scanners. FlexDock cups, power supply (851-095-121), and country-specific line cord must be ordered separately.	No
FlexDock Kit, Quad Charge 	DX2A28820	This comprehensive charge kit includes: two SF61B FlexDock cups, a FlexDock dual charge base, and a universal power supply. Must order country-specific line cord separately.	No

# SF61B

## Accessory Guide

### Holders and Chargers

Accessory Name	Part Number	Description	Backward Compatible with SF51
AC Charger, Single Bay 	SF61-APK-S001	Charge a single SF61B mobility scanner. Must order country-specific line cords separately.	No
Vehicle Power Adapter Kit 	SF61-VPK-S001	Includes a scanner holder, cable and 12V DC power socket for connecting to your vehicle's power accessory (cigar lighter) port. Charges a single scanner.	No

### Cables and Accessories

Accessory Name	Part Number	Description	Backward Compatible with SF51
Spare Battery 	SF61-BAT-S001	To extend the long-term service life of the scanner, this 2,600 mAh spare battery can be installed in the field.	No
Universal Power Supply 	851-089-306	This 5V DC power supply provides scanner power for use when host device power alone is insufficient. Includes ferrite (level V). Must order country-specific line cords separately.	Yes
Universal Power Supply for Quad Bay Charger 	851-088-201	Power supply for use with the quad-bay charger only (part number 871-222-001). Must order country-specific line cords separately.	Yes
FlexDock Quad Base Power Supply 	851-064-327	A 100W power supply for use with the FlexDock Quad base. Requires country-specific line cord to be ordered separately.	Yes
FlexDock Dual Base Power Supply 	851-095-121	A 48W power supply for use with the FlexDock Dual base. Requires country-specific line cord to be ordered separately.	Yes



[www.L-TronDirect.com](http://www.L-TronDirect.com)

800-830-9523

[info@L-Tron.com](mailto:info@L-Tron.com)

596 Fishers Station Dr | Victor, NY | 14564 | Suite 1 A

[www.L-Tron.com](http://www.L-Tron.com)

Get in touch with us  
on social media!

