

SF61B

Accessory Guide

Wearables

Accessory Name	Part Number	Description	Backward Compatible with SF51
Magnet End-Cap and Belt Loop	SF61-MAG-S001	This two-piece kit secures the scanner to your belt with magnetic force. Simply attach the belt loop with magnet to your belt, and affix the magnetic end-cap to the SF61B mobility scanner. This provides a quick and convenient attach/release method. A small plastic tool is included for installation/removal.	No
Ring End-Cap and Wrist Strap	SF61-RIN-S001	This two-piece kit includes a end-cap with ring that affixes to the SF61B mobility scanner, and a convenient wrist strap with cord-tightener. Simply thread the wrist strap through the ring, and the scanner can be conveniently worn around your wrist or arm--yet easily stowed away when both hands are needed. A small plastic tool is included for installation/removal.	No
Belt Loop, Standard	825-171-002	Belt loop with snap closure, allowing the SF61B to be conveniently attached to your belt. Note: Does not include the scanner magnet end-cap (see SF61-MAG-S001 for the entire kit).	Yes
Belt Clip, Industrial	825-172-002	A more heavy-duty version of the above belt loop, this industrial clip allows the SF61B to be conveniently attached to your belt. Note: Does not include the scanner magnet end-cap (see SF61-MAG-S001).	Yes
Chest Strap Holder	825-173-002	Designed for high-volume scanning in the DC or warehouse, this chest strap includes an adjustable waist with heavy-duty side squeeze buckle, and suspender with magnetic attachment. Fully adjustable.	Yes

SF61B

Accessory Guide



Holders and Chargers

Accessory Name	Part Number	Description	Backward Compatible with SF51
USB Charger, Single Bay 	SF61-UPK-S001	Charge a single SF61B mobility scanner via a USB port. (Requires a minimum 5V power source.)	No
Charge Cradle, Single Bay 	871-221-001	Charge cradle accommodates a single SF61B or SF51 mobility scanner. Includes a mounting plate for fixed-mounting onto a countertop or wall. Separate power supply (851-089-306) must be purchased separately.	Yes
Charge Cradle, Quad Bay 	871-222-001	Charge cradle accommodates up to four SF61B or SF51 mobility scanners. Includes a mounting plate for fixed-mounting onto a countertop or wall. Separate power supply (851-088-201) must be purchased separately.	Yes
FlexDock Cup, Dual Charge 	213-007-001	Supports the charging of two SF61B scanners when snapped into the bay of a FlexDock base (ordered separately--see below).	No
FlexDock Base, Quad Charge 	852-916-001	Provides four bays for charging. When combined with the FlexDock dual-charge cup above, this base can support the simultaneous charging of up to eight SF61B mobility scanners. FlexDock cups, power supply (851-064-327), and country-specific line cord must be ordered separately.	No
FlexDock Base, Dual Charge 	852-918-001	Provides two bays for charging. When combined with the FlexDock dual-charge cup above, this base can support the simultaneous charging of up to four SF61B mobility scanners. FlexDock cups, power supply (851-095-121), and country-specific line cord must be ordered separately.	No
FlexDock Kit, Quad Charge 	DX2A28820	This comprehensive charge kit includes: two SF61B FlexDock cups, a FlexDock dual charge base, and a universal power supply. Must order country-specific line cord separately.	No

SF61B

Accessory Guide

Holders and Chargers

Accessory Name	Part Number	Description	Backward Compatible with SF51
AC Charger, Single Bay 	SF61-APK-S001	Charge a single SF61B mobility scanner. Must order country-specific line cords separately.	No
Vehicle Power Adapter Kit 	SF61-VPK-S001	Includes a scanner holder, cable and 12V DC power socket for connecting to your vehicle's power accessory (cigar lighter) port. Charges a single scanner.	No

Cables and Accessories

Accessory Name	Part Number	Description	Backward Compatible with SF51
Spare Battery 	SF61-BAT-S001	To extend the long-term service life of the scanner, this 2,600 mAh spare battery can be installed in the field.	No
Universal Power Supply 	851-089-306	This 5V DC power supply provides scanner power for use when host device power alone is insufficient. Includes ferrite (level V). Must order country-specific line cords separately.	Yes
Universal Power Supply for Quad Bay Charger 	851-088-201	Power supply for use with the quad-bay charger only (part number 871-222-001). Must order country-specific line cords separately.	Yes
FlexDock Quad Base Power Supply 	851-064-327	A 100W power supply for use with the FlexDock Quad base. Requires country-specific line cord to be ordered separately.	Yes
FlexDock Dual Base Power Supply 	851-095-121	A 48W power supply for use with the FlexDock Dual base. Requires country-specific line cord to be ordered separately.	Yes



www.L-TronDirect.com

800-830-9523

info@L-Tron.com

596 Fishers Station Dr | Victor, NY | 14564 | Suite 1 A

www.L-Tron.com

Get in touch with us
on social media!

